

Agenda Item 11

Repairs to Bowling Pavillion:

Water Leak: For the third year in a row a leak has occurred when the water has been turned on in spring. The repair has been completed on Monday 10th March and the water system turned off and drained down due to potential ground frosts during the week. The Clerk has informed the Bowling Secretary that these repairs have been carried out and to not turn the water on until the threat of ground frosts has passed. The problem the Clerk believes is incorrect draining of system after the water has been turned off. The Council could turn the water off and drain the system as part of the use of the Pavillion on Remembrance Sunday, or earlier if there are forecasts of sub-zero temperatures earlier. The cost of the materials and repairs was £60.00

Internal Lighting at the Bowling Pavillion: The main room has two fluorescent lights and one emergency light whilst the kitchen has one fluorescent light with the two toilets having ceiling roses and bulb holders. These were fitted in the early 1980's when the pavilion was built with faults to two of the fluorescent lights, probable failure on the emergency light the Clerk is suggesting that the light units be upgraded to new LED lighting units to save electricity costs, the cost of the light units will be approximately £160.00 plus vat.